



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO0242

Work Order Type: Weatherization

Audit Name: 14014SO0242

CLIENT INFORMATION

Client Name:

Address:

Client ID: 14014SO0242

Shelbyville, TN 37160

Alt. Client ID: Bedford

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY

Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY
FAYETTEVILLE, TN 37334-2001

Fax: (931) 438-0074

Email Address: e.satterfield@schra.us

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO0242

Alt. Client ID: Bedford

Work Order (Bid Form)

Work Order Name: 14014SO0242

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 5

Measures

Measure 1 Infiltration Redctn

Components HS1

Inspected

Comment replace sill South wall 24x39
W/S back double door
W/S front door
W/S attic access and install 2 latches
install crawlspace excess door
reduce infiltration by 325 CFM @ 50 to target
Install crawlspace access door

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Supplies	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	labor	Each		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Measure 2 DWH Pipe Insulation

Components

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 14014SO0242

Alt. Client ID: Bedford

Work Order (Bid Form)

Work Order Name: 14014SO0242

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 5

Measure 3 Attic Ins. R-30**Components A1****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1632	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Attic Insulation - Blown Cellulose - R-30	SqFt	1632	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 Floor Ins. R-19****Components F1****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1632	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1632	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO0242

Alt. Client ID: Bedford

Work Order (Bid Form)

Work Order Name: 14014SO0242

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 5

Measure 5 Fix Improper Venting (Clothes Dryer)				Components			Inspected		
Comment							<input type="checkbox"/>		

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Fix improper venting	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	labor	Each		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:
Sub Total:

Field Notes:

Measure 6 Fix Improper Venting of Bathroom Exhaust Fan				Components			Inspected		
Comment							<input type="checkbox"/>		

repair exhaust fan in bathroom and pipe bathroom exhaust to eve with a slope

#	Material / Labor	Description / Comment	Units	Estimated		Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost
1	Health and Safety Items	Bathroom exhaust	Each		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	labor	Each		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:
Sub Total:

Field Notes:

Measure 8 Smoke Detector is Needed				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	smoke combo	Each						
2	Labor	labor	Each						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 9 Vapor Barrier Needed (Basement/Crawlspace)				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	install ground cover	SqFt	1632					
2	Labor	labor	SqFt						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Work Order Grand Total:		Grand Total:	
-------------------------	--	--------------	--